



1 Pace Plaza East Renovation - Progress Photos





LV Balcony concrete formwork is ongoing.



Gypsum wall installation on the Podium floors.

1 Pace Plaza East Renovation - Progress Photos



New Stair J installation overlooking the Brooklyn Bridge.

1 Pace Plaza East Renovation - Progress Photos



4th Floor mechanical equipment crane operation is complete.

1 Pace Plaza East Renovation - Progress Photos



Bathroom tile mock-up in Maria's Tower Bathrooms.