


1 Pace Plaza East Renovation - Progress Photos



Orchestra level seating from cellar view.




New freight elevator steel installation is ongoing.

1 Pace Plaza East Renovation - Progress Photos




Gyp wall installation in the Large Venue dance rehearsal.



2nd Floor Studio Spaces.

1 Pace Plaza East Renovation - Progress Photos



Framing and ductwork installation continues throughout the Podium floors.