

1 Pace Plaza East Renovation - Progress Photos



Successful crane operation was completed on May 4

1 Pace Plaza East Renovation - Progress Photos




Successful crane operation was completed on May 4

1 Pace Plaza East Renovation - Progress Photos



Ongoing concrete formwork in the Schimmel Theatre.

1 Pace Plaza East Renovation - Progress Photos





Garden level view of stage.



Schimmel Balcony view from stage.

1 Pace Plaza East Renovation - Progress Photos



1st floor concrete self-leveling is ongoing.

1 Pace Plaza East Renovation - Progress Photos



Large Dance Rehearsal wall framing progression.



Gyp wall installation continues throughout the Podium floors.