

1 Pace Plaza East Renovation - Progress Photos



Progress in the Schimmel Theatre.

1 Pace Plaza East Renovation - Progress Photos




Podium mechanical, gypsum wall and other interior work continues.

1 Pace Plaza East Renovation - Progress Photos



Progress in the future Maker Space on the 3rd Floor.



1 Pace Plaza East Renovation - Progress Photos



Installation of Maria's Tower corridor ceiling tiles and lights.



Maria's Tower elevator lobby door installation.

1 Pace Plaza East Renovation - Progress Photos



18th Floor of Maria's Tower gypsum wall and other interior work continues.