


1 Pace Plaza East Renovation - Progress Photos



Foam and rebar installation in preparation for the Basement slab concrete pour.

1 Pace Plaza East Renovation - Progress Photos




Gypsum wall installation and other finish trades continue throughout the Podium floors.

1 Pace Plaza East Renovation - Progress Photos




Ceiling conduit installation and painting are ongoing on the Podium floors.

1 Pace Plaza East Renovation - Progress Photos



Framework installation around Stair J.



Podium corridor framing is ongoing throughout.

1 Pace Plaza East Renovation - Progress Photos



The team attended a light fixture dimming test at City Theatrical to review the dimming of the Large Venue lights.