

1 Pace Plaza East Renovation - Progress Photos



Progress in the Schimmel Theatre – lower seating well CMU installation.

1 Pace Plaza East Renovation - Progress Photos




Schimmel Theatre Grid Iron – Loft Block installation.




Schimmel Theatre Rigging to start 7/21/25.

1 Pace Plaza East Renovation - Progress Photos



Progress of painting in the Schimmel Theatre.

1 Pace Plaza East Renovation - Progress Photos



Progress in the Large Dance Rehearsal.

1 Pace Plaza East Renovation - Progress Photos



Podium floors framing and MEP overhead installation are ongoing. Duct & Riser testing ongoing.