

# 1 Pace Plaza East Renovation - Progress Photos




Schimmel Theatre Grid Iron & Truss



# 1 Pace Plaza East Renovation - Progress Photos



Small Venue framing and ductwork installation is ongoing.




Medium Venue catwalk railing painting in progress.



## 1 Pace Plaza East Renovation - Progress Photos




Progress of bathrooms in the Podium floors.



3<sup>rd</sup> floor framing is ongoing.

## 1 Pace Plaza East Renovation - Progress Photos



Maria's Tower bathroom mock-up in progress.