

1 Pace Plaza East Renovation - Progress Photos



Progress in the Schimmel Theatre.

1 Pace Plaza East Renovation - Progress Photos




Progress in the Schimmel Theatre. Ceilings in the venue will start to close this week, permanent lighting, railings and chains are being installed.

1 Pace Plaza East Renovation - Progress Photos




Catwalk install substantially complete, safety railings to be installed week of 6/30.

1 Pace Plaza East Renovation - Progress Photos



Framing on the ground floor continues along with topping slab pours outside of the Small Venue.

1 Pace Plaza East Renovation - Progress Photos



1st Floor concrete topping slab installation.

1 Pace Plaza East Renovation - Progress Photos



MEP overhead installation is ongoing on the Podium floors.