


1 Pace Plaza East Renovation - Progress Photos



Courtyard EIFS & Façade system installation has begun.





Courtyard Chaim Gross Sculpture has been relocated.

1 Pace Plaza East Renovation - Progress Photos



1st Floor Sands College Sound Stage progression

1 Pace Plaza East Renovation - Progress Photos



2nd Floor Medium Venue progression

1 Pace Plaza East Renovation - Progress Photos



4th Floor roof duct installation continues.



Exhaust for Spray-paint booth.