



# 1 Pace Plaza East Renovation - Progress Photos



Concrete and masonry progress in Schimmel Theatre.



## 1 Pace Plaza East Renovation - Progress Photos



Perimeter walls at Schimmel Theatre at Garden level.



Framing and MEP installation throughout the Podium continue.



## 1 Pace Plaza East Renovation - Progress Photos



Maria's Tower bathroom mock-up in progress.

# 1 Pace Plaza East Renovation - Progress Photos



4<sup>th</sup> Floor Roof - New ductwork that services new rooftop equipment.