




## 1 Pace Plaza East Renovation - Progress Photos



Pace Development Team touring the Blackbox and Schimmel Theaters.



## 1 Pace Plaza East Renovation - Progress Photos




Installation of theater equipment is ongoing in the Schimmel Theater.



## 1 Pace Plaza East Renovation - Progress Photos



Installation of strong points in Large Dance Rehearsal is complete.



General progress of interior fitout in rehearsal studio.

## 1 Pace Plaza East Renovation - Progress Photos



Installation of interior partitions, ceiling, and MEPs in continuing in the new Scene Shop.