



1 Pace Plaza East Renovation - Progress Photos



Courtyard East Elevation waterproofing installation is ongoing.

1 Pace Plaza East Renovation - Progress Photos




Small Venue overhead conduit installation is ongoing.

1 Pace Plaza East Renovation - Progress Photos




Progress in the Film & Screen Studies checkout room and 2nd Floor corridor.

1 Pace Plaza East Renovation - Progress Photos



IDF closet progress on Podium floors.



2nd Floor Studios.

1 Pace Plaza East Renovation - Progress Photos



Maria's Tower Bathroom accessories have been installed for the mock-up bathroom.