




1 Pace Plaza East Renovation - Progress Photos



Schimmel Theatrical rigging system is being installed – line sets and battens are being hung!

1 Pace Plaza East Renovation - Progress Photos




Schimmel Theatre continues to progress.

1 Pace Plaza East Renovation - Progress Photos



Film & Screen Studies Soundstage





New Stair J installation progress.

1 Pace Plaza East Renovation - Progress Photos





Progress in the Film & Screen Studies checkout room and 2nd Floor corridor.

1 Pace Plaza East Renovation - Progress Photos



3rd Floor Animation Studio progress.

1 Pace Plaza East Renovation - Progress Photos



Maria's Tower elevator lobby & portal mockup review.