



1 Pace Plaza East Renovation - Progress Photos



Courtyard Façade progression, support steel being installed for decorative screen.




The Spruce Street Stoop Stairs.

1 Pace Plaza East Renovation - Progress Photos



Schimmel Theatrical scaffolding quick deck has been removed!

1 Pace Plaza East Renovation - Progress Photos




Garden Floor Screening Room progress.

1 Pace Plaza East Renovation - Progress Photos



1st Floor scene shop progress.

1 Pace Plaza East Renovation - Progress Photos



Progress on the Podium corridor and Sands studios.

1 Pace Plaza East Renovation - Progress Photos



Maria's Tower 18th Floor Amenity Space.



Maria's Tower Corridor progression.