


1 Pace Plaza East Renovation - Progress Photos



Installation of theater equipment is ongoing in Schimmel Theater fly tower.

1 Pace Plaza East Renovation - Progress Photos



Schimmel Theater progress.

1 Pace Plaza East Renovation - Progress Photos



Classroom and rehearsal studio progress.

1 Pace Plaza East Renovation - Progress Photos



Podium bathroom progress.

1 Pace Plaza East Renovation - Progress Photos



Maria's Tower Typical Bathroom progress.



Maria's Tower 18th Floor Corridor progress.