

1 Pace Plaza East Renovation - Progress Photos



Ongoing installation of new exterior façade systems on Gold St and Courtyard.


1 Pace Plaza East Renovation - Progress Photos



Installation of theater finishes and equipment are ongoing throughout Schimmel Theater.



1 Pace Plaza East Renovation - Progress Photos




Grand Stair and new Café progress in the Cellar.

1 Pace Plaza East Renovation - Progress Photos



Garden Theater and Schimmel Theater Scene Dock progress.

1 Pace Plaza East Renovation - Progress Photos



Costume Shop and typical Studio Classroom progress.

1 Pace Plaza East Renovation - Progress Photos



Typical hallway and Student Lounge progress.