




1 Pace Plaza East Renovation - Progress Photos



Installation of theater finishes and equipment are ongoing throughout Schimmel Theater.



1 Pace Plaza East Renovation - Progress Photos



Schimmel Theater progress.

1 Pace Plaza East Renovation - Progress Photos




Progress in the cellar mechanical and electrical spaces.

1 Pace Plaza East Renovation - Progress Photos



Film Equipment Room progression.



1 Pace Plaza East Renovation - Progress Photos



3rd Floor Classroom light fixture, ceiling and flooring installation continue.

1 Pace Plaza East Renovation - Progress Photos



Podium light fixture and cable tray installation continues throughout corridors.