



1 Pace Plaza East Renovation - Progress Photos




Garden floor entry storefront installation is ongoing.



1 Pace Plaza East Renovation - Progress Photos



Installation of theater finishes and equipment are ongoing throughout Schimmel Theater.



1 Pace Plaza East Renovation - Progress Photos



Campus Planning on stage at Schimmel Theater.

1 Pace Plaza East Renovation - Progress Photos




Studio Spaces & Audio Video Shop progression.

1 Pace Plaza East Renovation - Progress Photos



3rd Floor Animation Studio.



1 Pace Plaza East Renovation - Progress Photos



Maria's Tower Dormitory floors are working towards target punchlist dates.