


1 Pace Plaza East Renovation - Progress Photos



Schimmel Theater progress.

1 Pace Plaza East Renovation - Progress Photos



Studio Classroom, specialty flooring to be installed.

1 Pace Plaza East Renovation - Progress Photos



Screening Room Progress.




Large Dance Rehearsal Progress.

1 Pace Plaza East Renovation - Progress Photos




Dressing Room progress.



Maria's Tower corridors are being punch listed!

1 Pace Plaza East Renovation - Progress Photos



Small Dance Rehearsal and AV Room progress.