


# 1 Pace Plaza East Renovation - Progress Photos




*Continued progress in Schimmel Theater.*


# 1 Pace Plaza East Renovation - Progress Photos




*Millwork fins are being installed at the balcony level.*



# 1 Pace Plaza East Renovation - Progress Photos



*North Façade progress.*



*Stair progress.*

# 1 Pace Plaza East Renovation - Progress Photos




*University Relations & Marketing team tour the Black Box Theater.*

## 1 Pace Plaza East Renovation - Progress Photos




*Large Dance Rehearsal progress.*



*Ongoing stage flooring installation in rehearsal rooms.*

## 1 Pace Plaza East Renovation - Progress Photos



*Maria's Tower Dormitory – Final wax & sealing of floors.*