


# 1 Pace Plaza East Renovation - Progress Photos





*Courtyard mesh screen installation ongoing, upper screen complete!*

# 1 Pace Plaza East Renovation - Progress Photos



*Millwork detail installation in Schimmel Theater progresses.*

# 1 Pace Plaza East Renovation - Progress Photos




*Medium Venue progress, stage flooring to be installed.*

## 1 Pace Plaza East Renovation - Progress Photos




*2<sup>nd</sup> Floor Rehearsal Rooms*



*3<sup>rd</sup> Floor Classrooms*

## 1 Pace Plaza East Renovation - Progress Photos



*Maria's Tower dormitory floors are in the final stages of punchlisting by the design team.*

# 1 Pace Plaza East Renovation - Progress Photos



*Maria's Tower 18<sup>th</sup> Floor Amenity Space.*