

1 Pace Plaza East Renovation - Progress Photos




Courtyard mesh screen installation being finalized

1 Pace Plaza East Renovation - Progress Photos



Small Venue Progress



Medium Venue Stage Flooring Install

1 Pace Plaza East Renovation - Progress Photos




Café works ongoing with millwork install commenced

1 Pace Plaza East Renovation - Progress Photos



Podcast Studio



Communications and Media Studies Classroom

1 Pace Plaza East Renovation - Progress Photos



Makerspace ready for punch list