


1 Pace Plaza East Renovation - Progress Photos



BlackBox Theater progress




BlackBox acoustic wall installation

1 Pace Plaza East Renovation - Progress Photos



Screening Room progress



Blackbox Theater chair delivery

1 Pace Plaza East Renovation - Progress Photos



Carpet installation ongoing in 2nd floor lobby corridor



Restroom punchlist ongoing

1 Pace Plaza East Renovation - Progress Photos



Café millwork installation ongoing



Café progress