


1 Pace Plaza East Renovation - Progress Photos





Gold Street New Freight Car Ramp



*Cellar Kitchen Fiberglass Reinforced Plastic Wall Panels
Ongoing*

1 Pace Plaza East Renovation - Progress Photos



Cellar Café Millwork Installation

1 Pace Plaza East Renovation - Progress Photos



Residential Entry Turnstiles Installation




Spruce Street Stoop Ornamental Mesh Installation

1 Pace Plaza East Renovation - Progress Photos



Level 2 Rehearsal Room Floor Installation



Level 2 Podium Elevator Lobby

1 Pace Plaza East Renovation - Progress Photos



Level 18 Amenity Space Hood Installation