

1 Pace Plaza East Renovation - Progress Photos



View to Courtyard from 2nd Floor Offices




Level 2 Corridor Punch/ist Complete

1 Pace Plaza East Renovation - Progress Photos




Costume Shop Progress




3rd Floor Elevator Lobby Digital Screen Install.

1 Pace Plaza East Renovation - Progress Photos



Marias Tower Dorm Room Furniture Installation

1 Pace Plaza East Renovation - Progress Photos



Laundry install with washers and dryers